TT
497
C64

THE PROBLEM OF
SEAM STRENGTH AND THREAD DURABILTY

A REPORT ISSUED BY

THE CLOTHING MANUFACTURERS ASSOCIATION
OF THE UNITED STATES OF AMERICA
220 FIFTH AVENUE
NEW YORK 1, NEW YORK

September 1953

C.M.A.
PRODUCTION RESEARCH
REPORT #2

Digitized by Google

Original from
CORNELL UNIVERSITY

ALBERT R. MANN
LIBRARY

NEW YORK STATE COLLEGES
OF
AGRICULTURE AND HOME ECONOMICS

AT

CORNELL UNIVERSITY

Digitized by Google

Original from
CORNELL UNIVERSITY

Date Due

MAY 14 1973

Library Bureau Cat. No. 1137

Cornell University Library
TT 497.C64
The problem of seam strength and thread
3 1924 003 594 854

Digitized by Google

Original from
CORNELL UNIVERSITY

SOME ATTACHMENTS FOR OVERCOMING NEEDLE HEAT IN SEWING

Fig. 10 – Needle Cooler body



Fig. 11 – Needle Cooler nozzle



Fig. 12 – Needle lubricator



Fig. 13 – Thread lubricators



Digitized by Google

Original from
CORNELL UNIVERSITY

Digitized by Google
Original from
CORNELL UNIVERSITY

Digitized by Google
Original from
CORNELL UNIVERSITY

Digitized by Google

Original from
CORNELL UNIVERSITY